

**Reference Number:** FOI202223/405  
**From:** Commercial  
**Date:** 18 January 2023  
**Subject:** Clinical imaging equipment

Q1 Data on your Trust's clinical imaging equipment.

Can you please complete the fields in the attached spreadsheet with what you currently hold?

A1 [Please see attachment – 405 FOI Response](#)

<b>Trust name:</b>	<b>Liverpool Heart and Chest Hospital NHS Foundation Trust</b>	
	<b>MES Contract 1</b>	<b>MES Contract 2</b>
<b>Supplier</b>	Siemens Healthcare.	Information not held - No 2nd contract inplace
<b>Contract Start Date</b>	01/10/2019	
<b>Contract End Date</b>	01/10/2026	
<b>Initial Cost</b>	£272,544	
	Information not held - the Trust does not routinely collate or hold this information centrally as part of its management or performance data.	
<b>Interest rates (%)</b>		
<b>Consumables included?</b>	No	
<b>Accessories included?</b>	Yes	
<b>Maintenance included?</b>	Yes	

Asset ID	Local Identifier	Modality (drop-down list)	Manufacturer	Asset name	Equipment detail	No. of devices	Age	First in Service	Planned replacement date	Replacement schedule (drop-down list)	Ownership structure (drop-down list)	How is the ownership accounted for? (drop-down list)	Capital purchase cost	Maintenance type (drop-down list)	Maintenance provider	Maintenance Service Contract Start Date	Maintenance Service Contract End Date	Maintenance Cost	
4804	GB100275-034-001	Interventional Radiology	Philips Healthcare	Image Acquisition	Cardiac Single Plane	1	14	01/01/2009	01/01/2009	Decommissioned	Capital purchase (new)	Capital cost	57987	Supplier provides maintenance - Non Tube Inc					
4805	GB104433-08	Interventional Radiology	Philips Healthcare	Image Acquisition	Cardiac Bi-Plane	1	12	01/12/2010	01/12/2010	Decommissioned	Capital purchase (new)	Capital cost	82770	Supplier provides maintenance - Non Tube Inc					
4806	GB104433-27	Interventional Radiology	Philips Healthcare	Image Acquisition	Cardiac Single Plane	1	17	01/04/2006	01/04/2006	Replacement approved awaiting funds	Capital purchase (new)	Capital cost	69235	Supplier provides maintenance - Non Tube Inc					
4807	GB100275-032-001	Interventional Radiology	Philips Healthcare	Image Acquisition	Cardiac Bi-Plane	1	15	01/04/2007	01/04/2007	Replacement approved awaiting funds	Capital purchase (new)	Capital cost	79173	Supplier provides maintenance - Non Tube Inc					
4808	GB103026-18	Interventional Radiology	Philips Healthcare	Image Acquisition	Decommissioned	1	16	13/03/2006	13/03/2006	Decommissioned	Capital purchase (new)	Capital cost							
4809	R06DCBRD5K10096	CT	Siemens Healthcare	Image Acquisition	Decommissioned	1	10	01/04/2012	01/04/2012	Decommissioned	Capital purchase (new)	Capital cost	211200	External Maintenance - Non Tube Inc					
4810	GB104433-25	Plan XRay	Philips Healthcare	Image Acquisition	Plan X-Ray (DR Static)	1	16	13/03/2006	13/03/2006	Not due for replacement	Lease hold	Finance lease				01/04/2020	31/03/2024	£ 8,872.41	
4811	F45RD42	Plan XRay	Konica Minolta	Image Acquisition	Plan X-Ray (DR Static)	1	4	01/05/2018	01/05/2018	Not due for replacement	Lease hold	Finance lease				31.10.20	31.12.24		
4812	GB104433-30	Plan XRay	Philips Healthcare	Image Acquisition	Plan X-Ray (DR Static)	1	16	13/03/2006	13/03/2006	Replacement approved awaiting funds	Lease hold	Finance lease				01.04.20	31.03.25	£ 8,872.41	
4813	R06DSH4M48A	MRI	Siemens Healthcare	Image Acquisition	Wide Bore 1.5T	1	10	01/04/2012	01/04/2012	Not due for replacement	Capital purchase (new)	Capital cost	104360	External Maintenance - Non Tube Inc					
4814	K5240-9385	Plan XRay	Carestream Health	Image Acquisition	Plan X-Ray (DR Mobile)	1	8	01/04/2014	01/04/2014	Replacement approved awaiting funds	Capital purchase (new)	Capital cost	112500	External Maintenance - Non Tube Inc					
K5240-9387	Plan XRay	Carestream Health	Image Acquisition	Plan X-Ray (DR Mobile)		1	8	02/04/2014	02/04/2014	Not due for replacement	Capital purchase (new)	Capital cost	112500	External Maintenance - Non Tube Inc					
K5240-9388	Plan XRay	Carestream Health	Image Acquisition	Plan X-Ray (DR Mobile)		1	8	03/04/2014	03/04/2014	Not due for replacement	Capital purchase (new)	Capital cost	112500	External Maintenance - Non Tube Inc					
K5240-9389	Plan XRay	Carestream Health	Image Acquisition	Plan X-Ray (DR Mobile)		1	8	04/04/2014	04/04/2014	Not due for replacement	Capital purchase (new)	Capital cost	112500	External Maintenance - Non Tube Inc					
GB104433-18	Dental	Philips Healthcare	Image Acquisition	OPQ Machine (Dental)		1	16	13/03/2006	13/03/2006	No plans to replace this asset	Other	Other Owner responsibility				01.04.20	31.03.25	£ 3,120.34	
R06DSIEDUS370	Ultrasound	Siemens Healthcare	Image Acquisition	2D Ultrasound - General		1	16	13/03/2006	13/03/2006	Decommissioned	Capital purchase (new)	Capital cost	39240	Supplier provides maintenance - Non Tube Inc					
PUL01	Fluoroscopy	Philips Healthcare	Image Acquisition	Decommissioned		1	16	01/04/2006	01/04/2006	Decommissioned	Capital purchase (new)	Capital cost	104322	External Maintenance - Non Tube Inc					
GB100275-036-001	Fluoroscopy	Philips Healthcare	Image Acquisition	Mobile C-arm - Image Intensifier		1	16	01/04/2006	01/04/2006	Not due for replacement	Capital purchase (new)	Capital cost	116960	External Maintenance - Non Tube Inc					
F020LAB_B	Interventional Radiology	Philips Healthcare	Image Acquisition	Decommissioned		1	15	01/06/2007	01/06/2007	Decommissioned	Capital purchase (new)	Capital cost	64825	External Maintenance - Non Tube Inc					
R06DOPGCR0010026	Plan XRay	Carestream Health	Image Acquisition	Plan X-Ray (CR Static)		1	16	13/03/2006	13/03/2006	Not due for replacement	Lease hold	Finance lease							
47617	AdjunctAsset Accessory	Siemens Healthcare	Injector_Accessory	Pressure Injector (MRI)		1	10	01/04/2012	01/04/2012	Not due for replacement	Capital purchase (new)	Capital cost				29.08.21	28.08.22	3553.00	
SNR0013216-0415	AdjunctAsset Accessory	Other	Injector_Accessory	Decommissioned		1	7	01/07/2015	01/07/2015	Decommissioned	Loaned	Other Owner responsibility							
M69162	AdjunctAsset Accessory	Other	Injector_Accessory	Pressure Injector (MRI)		1	10	01/04/2012	01/04/2012	Not due for replacement	Capital purchase (new)	Capital cost							
M69431	AdjunctAsset Accessory	Other	Injector_Accessory	Pressure Injector (MRI)		1	10	01/04/2012	01/04/2012	Not due for replacement	Capital purchase (new)	Capital cost							
006-MP0000030	MRI	Siemens Healthcare	Image Acquisition	Wide Bore 3T		1	3	04/11/2019	04/11/2019	Not due for replacement	Managed Equipment Service	MES Contract				11/01/1900	11/01/1900		
C123341	AdjunctAsset Accessory	Other	Injector_Accessory	Pressure Injector (MRI)		1	3	04/11/2019	04/11/2019	Not due for replacement	Capital purchase (new)	Capital cost	20390	Supplier provides maintenance			28.04.22	01/04/2024	£ 3,853.00
006-CT00000800	CT	Siemens Healthcare	Image Acquisition	reconstruction	CT scanner with 64 detector rows or more but less than 256 detector rows with iterative	1	3	28/10/2019	28/10/2019	Not due for replacement	Managed Equipment Service	MES Contract				11/01/1900	11/01/1900		
C06136170-3118	AdjunctAsset Accessory	Other	Injector_Accessory	Pressure Injector (CT)		1	3	28/10/2019	28/10/2019	Not due for replacement	Loaned	Other Owner responsibility				11/01/1900	11/01/1900		
GB100275-057-001	Interventional Radiology	Philips Healthcare	Image Acquisition	Cardiac Single Plane		1	3	18/11/2019	18/11/2019	Not due for replacement	Capital purchase (new)	Capital cost							
CX23450	AdjunctAsset Accessory	Other	Injector_Accessory	Pressure Injector (MRI)		1	3	01/12/2019	01/12/2019	Not due for replacement	Capital purchase (new)	Capital cost	17500	Supplier provides maintenance					
A0311	Fluoroscopy	Philips Healthcare	Image Acquisition	Mobile C-arm - Image Intensifier		1	3	01/12/2019	01/12/2019	Not due for replacement	Capital purchase (new)	Capital cost	121000	Supplier provides maintenance			01.12.19	30.11.20	£ 29,170.00
GB100275-003-006	Interventional Radiology	Philips Healthcare	Image Acquisition	Hybrid Theatre (static)		1	3	01/11/2019	01/11/2019	Not due for replacement	Owned by Other Department	Other Owner responsibility							
EP0204843	AdjunctAsset Accessory	Other	Injector_Accessory	Power Injector (Angio)		1	7	01/08/2015	01/08/2015	Not due for replacement	Lease hold	Finance lease				28.04.22	27.04.23	£ 2,920.00	
525076	AdjunctAsset Accessory	Other	Injector_Accessory	Power Injector (Angio)		1	12	01/12/2010	01/12/2010	No plans to replace this asset	Lease hold	Finance lease				28.04.22	27.04.23	£ 2,920.00	
EP0021445	AdjunctAsset Accessory	Other	Injector_Accessory	Power Injector (Angio)		1	7	01/08/2015	01/08/2015	No plans to replace this asset	Lease hold	Finance lease				28.04.22	27.04.23	£ 2,920.00	
525069	AdjunctAsset Accessory	Other	Injector_Accessory	Power Injector (Angio)		1	15	01/01/2006	01/01/2006	Not due for replacement	Lease hold	Finance lease				28.04.22	27.04.23	£ 2,920.00	
527368	AdjunctAsset Accessory	Other	Injector_Accessory	Power Injector (Angio)		1	14	01/01/2009	01/01/2009	Not due for replacement	Lease hold	Finance lease				28.04.22	27.04.23	£ 2,920.00	
532538	AdjunctAsset Accessory	Other	Injector_Accessory	Power Injector (Angio)		1	11	01/01/2012	01/01/2012	Not due for replacement	Lease hold	Finance lease				28.04.22	27.04.23	£ 2,920.00	
GB104433-19	Fluoroscopy	Philips Healthcare	Image Acquisition	Fixed C-arm - Flat Panel Digital Detector		1	16	01/03/2006	01/03/2006	Due for replacement, Business Case pending	Lease hold	Other Owner responsibility				01.04.20	31.03.22	£ 69,100.00	
TUS-A77006L	Ultrasound	Canon	Image Acquisition	Ultrasound - General		1	0	31/03/2022	31/03/2022	Not due for replacement	Capital purchase (new)	Capital cost	75000	Supplier provides maintenance			23/02/2022	23/02/2024	£98,000.00
GB100275-056-001	Interventional Radiology	Philips Healthcare	Image Acquisition	Cardiac Single Plane		1	1	01/06/2021	01/06/2021	Not due for replacement	Capital purchase (new)	Capital cost							
T0020060-9818	AdjunctAsset Accessory	Siemens Healthcare	Injector_Accessory	Power Injector (CT)		1	1	03/04/2021	03/04/2021	Not due for replacement	Capital purchase (new)	Capital cost				18.10.21	17.10.24	£ 8,562.00	
GB100275-009-010	Interventional Radiology	Philips Healthcare	Image Acquisition	Cardiac Bi-Plane		1	1	01/06/2021	01/06/2021	Not due for replacement	Capital purchase (new)	Capital cost							
763371	CT	Siemens Healthcare	Image Acquisition	CT scanner with 64 detector rows or more but less than 256 detector rows		1	1	03/04/2021	03/04/2021	Not due for replacement	Capital purchase (new)	Capital cost	840000						
13226y7	Plan XRay	Carestream Health	Image Acquisition	Plan X-Ray (DR Mobile)		1	1	01/11/2021	01/11/2021	Not due for replacement	Capital purchase (refurbished)	Capital cost	£50000	Asset within warranty					